



Art Nadler, Public Information Officer
(702) 486-1100 x1139
or (775) 688-1141 x1139

16 NEVADA CONTRACTORS DISCIPLINED **BY CONTRACTORS BOARD**

(Reno, NV) – At its meeting on July 14, 2010, the Nevada State Contractors Board adjudicated cases involving 16 contractors.

Big Valley Landscaping, license number 39796 (Landscaping), based out of Gardnerville, NV, was found in violation of Nevada Revised Statute 624 for failure to take appropriate corrective action; failure to include the monetary license limit and license number on a contract or proposal; failure to include the Residential Recovery Fund information on a contract or proposal; acting in the capacity of a contractor beyond the scope of the license; failure to ascertain that each person whose bid on a construction project is appropriately licensed and failure to keep in force a bond or cash deposit. The licensee was fined \$800, ordered to pay investigative costs and take corrective action to make the homeowner whole. The license remains suspended.

Don Parsons Construction, LLC., license number 69869 (Residential & Small Commercial), based out of Fernley, NV, was found in violation of Nevada Revised Statute 624 for failure to keep in force a bond or cash deposit and failure to establish financial responsibility. The licensee was fined \$600; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

Kurt Karl Krug, dba Great Basin Deck & Shade, license numbers 72097 and 72813 (Awnings & Louvers and Carpentry, Remodeling & Repairs), based out of Carson City, NV, was found in violation of Nevada Revised Statute 624 for failure to take appropriate corrective action; failure to include the monetary license limit and license number on a contract or proposal; and acting in the capacity of a contractor beyond the scope of the license. The licensee was fined \$550; ordered to pay investigative costs and provide a current financial statement that supports the license limit.

Eagle Roofing, license number 54187 (Roofing), based out of Minden, NV, was found in violation of Nevada Revised Statute 624 for willful disregard of the laws of the state regarding industrial insurance; misrepresentation; failure to respond to a written request from the Board; and failure to establish financial responsibility. The licensee was fined \$2,250 and ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

Jacob William Felshaw, dba A B C Plumbing & Heating, license number 73412 (Plumbing and Heating Cooling Circulating Air), based out of Reno, NV, was found in violation of Nevada Revised Statute 624 for failure to respond to a written request from the Board; failure to comply with a written request from the Board; and failure to establish financial responsibility. The licensee was fined \$1,000 and ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

D Rokerries, license number 62225 (Unclassified and Rockery Walls Only), based out of Reno, NV, was found in violation of Nevada Revised Statute 624 for committing a fraudulent or deceitful act and failure to provide to establish financial responsibility. The licensee was fined \$2,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

David M Clements Painting, license number 69407 (Painting & Decorating), based out of Reno, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The license was suspended.

C M D Contracting, Inc., license number 70019 (Carpentry), based out of Colorado City, AZ, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility and failure to respond to a written request from the Board. The licensee was fined \$750; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

Fletcher Door & Trim, Inc., license number 72430 (Finish Carpentry), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility and failure to respond to a written request from the Board. The licensee was fined \$750; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was suspended.

Filakos, LLC., dba Glass Doctor of Las Vegas, license number 72455 (Glass & Glazing), based out of Gilbert, AZ, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility and failure to respond to a written request from the Board. The licensee was fined \$750; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

Jensen & Sons Construction of Nevada, LLC., license number 72519 (Residential & Small Commercial), based out of St. George, Utah, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility and failure to respond to a written request from the Board. The licensee was fined \$750; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

Southwestern Floors, LLC., dba Nevada Southwestern Floors, license numbers 72625 and 72627 (Finish Carpentry, Wood Floors and Tiling), based out of Tempe, AZ, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility and failure to respond to a written request from the Board. The licensee was fined \$750; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The licenses were revoked.

Advanced Home Theater, dba Accelerated Home Theater license number 72800 (Low Voltage), based out of North Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility and failure to respond to a written request from the Board. The licensee was fined \$750; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

Genoa Peak Electric, Inc. license number 69774 (Electrical), based out of Genoa, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility and failure to respond to a written request from the Board. The licensee was fined \$750; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was suspended.

Blue Rock Development, Inc., license number 72433 (Residential & Small Commercial), based out of Incline Village, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The licensee was ordered to pay previously ordered fines. The license was suspended.

Equivest Services E I S, Ltd., license number 69943 (Residential & Small Commercial), based out of Carson City, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The licensee was fined \$500 and ordered to pay investigative costs.

****The Business Review Program is one in which a contractor's business practices and regulatory compliance is examined by NSCB investigative staff. The program is a part of NSCB's proactive investigative efforts.**

The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.